

Project

Project Name: Castlewood Business Park- Plot 8
Project Description: WinCan Import in Miraculix Standard
Project Date: 21/07/2022



winvic

Table of Contents

Project Name	Project Number	Project Date
Castlewood Business Park- Plot 8		21/07/2022

Project Information	P-1
Scoring Summary	P-2
Section Item 1: SVP 1 > FMH07 (SVP 1X)	1
Section Item 2: FMH07 > FMH08 (FMH07X)	2
Section Item 3: FMH08 > FMH09 (FMH08X)	3
Section Item 4: FMH09 > FMH 10 (FMH09X)	4
Section Item 5: SVP 2 > FIC01 (SVP2X)	5
Section Item 6: FIC01 > FIC02 (FIC01X)	6
Section Item 7: FIC02 > FIC03 (FIC02X)	7
Section Item 8: FIC03 > FMH01 (FIC03X)	8
Section Item 9: SVP 4 > FMH01 (SVP4X)	9
Section Item 10: FMH01 > FMH02 (FMH01X)	10
Section Item 11: SVP05 > FMH02 (SVP05X)	11
Section Item 12: FMH02 > FMH03 (FMH02X)	12
Section Item 13: SVP06 > FMH03 (SVP06X)	13
Section Item 14: FMH03 > FMH04 (FMH03X)	14
Section Item 15: SVP07 > FMH04 (SVP07X)	15
Section Item 16: FMH04 > FMH04A (FMH04X)	16
Section Item 17: SVP 8 > FMH04A (SVP8X)	17
Section Item 18: FMH04A > FMH05 (FMH04AX)	18
Section Item 19: FMH05 > FMH06 (FMH05X)	19
Section Item 20: SIC01 > SMH01 (SIC01X)	20
Section Item 21: ACO1 > SMH01 (ACO1X)	21
Section Item 22: SMH01 > SMH04 (SMH01X)	22
Section Item 23: ACO2 > SMH03 (ACO2X)	23
Section Item 24: SMH03 > SMH04 (SMH03X)	24
Section Item 25: SMH04 > SMH05 (SMH04X)	25
Section Item 26: ACO3 > SMH05 (ACO3X)	26
Section Item 27: SMH05 > SMH06 (SMH05X)	27

Table of Contents

Project Name	Project Number	Project Date
Castlewood Business Park- Plot 8		21/07/2022

Section Item 28: G1 > SMH06 (G1X)	28
Section Item 29: G2 > SMH06 (G2X)	29
Section Item 30: ACO4 > SMH06 (ACO4X)	30
Section Item 31: SMH06 > SMH07 (SMH06X)	31
Section Item 32: ACO5 > SMH07 (ACO5X)	32
Section Item 33: SMH07 > INT2 (SMH07X)	33
Section Item 34: INT2 > SMH17 (INT2X)	34
Section Item 35: ACO7 > SMH08 (ACO7X)	35
Section Item 36: ACO8 > SMH08 (ACO8X)	36
Section Item 37: PSO3 > SMH08 (PSO3X)	37
Section Item 38: SMH08 > SMH09 (SMH08X)	38
Section Item 39: SMH09 > SMH11 (SMH09X)	39
Section Item 40: PSO1 > SMH10 (PSO1X)	40
Section Item 41: PSO2 > SMH10 (PSO2X)	41
Section Item 42: SMH10 > SMH11 (SMH10X)	42
Section Item 43: SMH11 > SMH16 (SMH11X)	43
Section Item 44: ACO10 > SMH13 (ACO10X)	44
Section Item 45: SMH13 > INT1 (SMH13X)	45
Section Item 46: INT1 > SWMH16 (INT1X)	46
Section Item 47: G6 > SWMH15 (G6X)	47
Section Item 48: G8 > SWMH15 (G8X)	48
Section Item 49: G9 > SWMH15 (G9X)	49
Section Item 50: G10 > SWMH15 (G10X)	50
Section Item 51: SMH15 > SMH16 (SMH15X)	51
Section Item 52: SMH16 > SMH17 (SMH16X)	52
Section Item 53: SMH17 > SMH18 (SMH17X)	53

Project Information

Project Name	Project Number	Project Date
Castlewood Business Park- Plot 8		21/07/2022

Client

Company: Winvic Construction LTD
Contact: Brampton House
Department: 19 Tenter Road
Street: Moulton Park
Town or City: Northampton
County: Northamptonshire
Post Code: NN3 6PZ
Phone: 01604 671021

**winvic**

Site

Company: Winvic Construction
Description: CCTV Drainage Survey
Contact: David Gilbert
Department: Vertical Build
Street: Plot 8
Town or City: Castlewood

Contractor

Company: Oakley Industrial Services LTD
Description: CCTV Drainage Surveys
Contact: Colin Clarke
Department: Drainage
Street: Enterprise Park
Town or City: Corby
County: Northants
Post Code: NN17 5JE
Phone: 01536 206179
Mobile: 07747 844248
Email: colin@theoakleygroup.com



Scoring Summary

Project Name Castlewood Business Park- Plot 8	Project Number	Project Date 21/07/2022
---	-----------------------	-----------------------------------

Structural Defects

Section	PLR	Grade	Description
All inspected pipes are in an acceptable structural condition (< grade 3).			

Service / Operational Condition

Section	PLR	Grade	Description
All inspected pipes are in an acceptable service condition (< grade 3).			

Abandoned Surveys

Section	PLR	Description
All inspections complete, none are abandoned.		

Information


These scoring summaries are based on the SRM grading from the WRc.

Section Inspection - 26/05/2022 - SVP 1X

Item No. 1	Insp. No. 1	Date 26/05/22	Time 8:30	Client's Job Ref CASTLEWOOD	Weather No Rain Or Snow	Pre Cleaned Yes	PLR SVP 1X
Operator JC		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Not Specified	Alternative ID 1

Town or Village:	Nottingham	Inspection Direction:	Upstream	Upstream Node:	SVP 1
Road:	Plot 8	Inspected Length:	5.83 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	5.83 m	Downstream Node:	FMH 07
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	150 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Post completion condition survey	Lining Material:	No Lining		

Comments:
Recommendations:




Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Section Inspection - 26/05/2022 - FMH 07X

Item No. 2	Insp. No. 4	Date 26/05/22	Time 9:12	Client's Job Ref CASTLEWOOD	Weather No Rain Or Snow	Pre Cleaned Yes	PLR FMH 07X
Operator JC		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Not Specified	Alternative ID 1

Town or Village:	Nottingham	Inspection Direction:	Upstream	Upstream Node:	FMH 07
Road:	Plot 8	Inspected Length:	81.39 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	81.39 m	Downstream Node:	FMH 08
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	150 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Post completion condition survey	Lining Material:	No Lining		

Comments:
Recommendations:




Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	0.0	0	0.0	0.0	0.0	0.0

Section Inspection - 27/05/2022 - FMH 08X

Item No. 3	Insp. No. 19	Date 27/05/22	Time 8:51	Client's Job Ref CASTLEWOOD	Weather No Rain Or Snow	Pre Cleaned Yes	PLR FMH 08X
Operator JC		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Not Specified	Alternative ID 1

Town or Village:	Nottingham	Inspection Direction:	Downstream	Upstream Node:	FMH 08
Road:	Plot 8	Inspected Length:	87.99 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	87.99 m	Downstream Node:	FMH 09
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	150 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Post completion condition survey	Lining Material:	No Lining		

Comments:
Recommendations:




Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	0.0	0	0.0	0.0	0.0	0.0

Section Inspection - 27/05/2022 - FMH 09X

Item No. 4	Insp. No. 5	Date 27/05/22	Time 9:17	Client's Job Ref CASTLEWOOD	Weather No Rain Or Snow	Pre Cleaned Yes	PLR FMH 09X
Operator MT		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Not Specified	Alternative ID 1

Town or Village:	Nottingham	Inspection Direction:	Downstream	Upstream Node:	FMH 09
Road:	Plot 8	Inspected Length:	48.50 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	48.50 m	Downstream Node:	FMH 10
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	150 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Post completion condition survey	Lining Material:	No Lining		

Comments:
Recommendations:



Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	0.0	0	0.0	0.0	0.0	0.0

Section Inspection - 26/05/2022 - SVP 2X

Item No. 5	Insp. No. 2	Date 26/05/22	Time 10:44	Client's Job Ref CASTLEWOOD	Weather No Rain Or Snow	Pre Cleaned Yes	PLR SVP 2X
Operator JC		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Not Specified	Alternative ID 1

Town or Village:	Nottingham	Inspection Direction:	Upstream	Upstream Node:	SVP 2
Road:	Plot 8	Inspected Length:	2.83 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	2.83 m	Downstream Node:	FIC 01
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	150 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Post completion condition survey	Lining Material:	No Lining		

Comments:
Recommendations:

Scale:	1:50	Position [m]	Code	Observation	MPEG	Photo	Grade
		Depth: m					
		FIC 01					
		0.00	MH	Start node, manhole, reference: FIC 01	00:00:00		
		0.00	WL	Water level, 0% of the vertical dimension	00:00:01		
		2.83	BRF	Finish node, major connection without manhole, reference: SVP 2	00:00:21		
		SVP 2					
		Depth: m					


Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	0.0	0	0.0	0.0	0.0	0.0

Section Inspection - 26/05/2022 - FIC 01X

Item No. 6	Insp. No. 3	Date 26/05/22	Time 10:46	Client's Job Ref CASTLEWOOD	Weather No Rain Or Snow	Pre Cleaned Yes	PLR FIC 01X
Operator JC		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Not Specified	Alternative ID 1

Town or Village:	Nottingham	Inspection Direction:	Downstream	Upstream Node:	FIC 01
Road:	Plot 8	Inspected Length:	24.06 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	24.06 m	Downstream Node:	FIC 02
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Post completion condition survey	Lining Material:	No Lining		

Comments:
Recommendations:




Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	0.0	0	0.0	0.0	0.0	0.0

Section Inspection - 26/05/2022 - FIC 02X

Item No. 7	Insp. No. 4	Date 26/05/22	Time 10:57	Client's Job Ref CASTLEWOOD	Weather No Rain Or Snow	Pre Cleaned Yes	PLR FIC 02X
Operator JC		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Not Specified	Alternative ID 1

Town or Village:	Nottingham	Inspection Direction:	Upstream	Upstream Node:	FIC 02
Road:	Plot 8	Inspected Length:	13.19 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	13.19 m	Downstream Node:	FIC 03
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Post completion condition survey	Lining Material:	No Lining		

Comments:
Recommendations:




Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	0.0	0	0.0	0.0	0.0	0.0

Section Inspection - 26/05/2022 - FIC 03X

Item No. 8	Insp. No. 7	Date 26/05/22	Time 11:52	Client's Job Ref CASTLEWOOD	Weather No Rain Or Snow	Pre Cleaned Yes	PLR FIC 03X
Operator JC		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Not Specified	Alternative ID 1

Town or Village:	Nottingham	Inspection Direction:	Downstream	Upstream Node:	FIC 03
Road:	Plot 8	Inspected Length:	8.86 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	8.86 m	Downstream Node:	FMH 01
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Post completion condition survey	Lining Material:	No Lining		

Comments:
Recommendations:




Section Inspection - 26/05/2022 - SVP 4X

Item No. 9	Insp. No. 5	Date 26/05/22	Time 11:44	Client's Job Ref CASTLEWOOD	Weather No Rain Or Snow	Pre Cleaned Yes	PLR SVP 4X
Operator JC		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Not Specified	Alternative ID 1

Town or Village:	Nottingham	Inspection Direction:	Upstream	Upstream Node:	SVP 4
Road:	Plot 8	Inspected Length:	3.88 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	3.88 m	Downstream Node:	FMH 01
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Post completion condition survey	Lining Material:	No Lining		

Comments:
Recommendations:



STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	0.0	0	0.0	0.0	0.0	0.0

Section Inspection - 26/05/2022 - FMH 01X

Item No. 10	Insp. No. 6	Date 26/05/22	Time 11:49	Client's Job Ref CASTLEWOOD	Weather No Rain Or Snow	Pre Cleaned Yes	PLR FMH 01X
Operator JC		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Not Specified	Alternative ID 1

Town or Village:	Nottingham	Inspection Direction:	Downstream	Upstream Node:	FMH 01
Road:	Plot 8	Inspected Length:	5.49 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	5.49 m	Downstream Node:	FMH 02
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Post completion condition survey	Lining Material:	No Lining		

Comments:
Recommendations:



Section Inspection - 26/05/2022 - SVP 05X

Item No. 11	Insp. No. 8	Date 26/05/22	Time 11:59	Client's Job Ref CASTLEWOOD	Weather No Rain Or Snow	Pre Cleaned Yes	PLR SVP 05X
Operator JC		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Not Specified	Alternative ID 1

Town or Village:	Nottingham	Inspection Direction:	Upstream	Upstream Node:	SVP 05
Road:	Plot 8	Inspected Length:	0.00 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	0.00 m	Downstream Node:	FMH 02
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Post completion condition survey	Lining Material:	No Lining		

Comments:

Recommendations:

Scale:	1:50	Position [m]	Code	Observation	MPEG	Photo	Grade
		Depth: m					
		FMH 02					
							
		SVP 05					
		Depth: m					
							

Construction Features

Miscellaneous Features

Structural Defects

Service & Operational Observations


STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	0.0	0	0.0	0.0	0.0	0.0

Section Inspection - 26/05/2022 - FMH 02X

Item No. 12	Insp. No. 12	Date 26/05/22	Time 12:47	Client's Job Ref CASTLEWOOD	Weather No Rain Or Snow	Pre Cleaned Yes	PLR FMH 02X
Operator JC		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Not Specified	Alternative ID 1

Town or Village:	Nottingham	Inspection Direction:	Upstream	Upstream Node:	FMH 02
Road:	Plot 8	Inspected Length:	15.36 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	15.36 m	Downstream Node:	FMH 03
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Post completion condition survey	Lining Material:	No Lining		

Comments:
Recommendations:




Section Inspection - 26/05/2022 - SVP 06X

Item No. 13	Insp. No. 14	Date 26/05/22	Time 14:26	Client's Job Ref CASTLEWOOD	Weather No Rain Or Snow	Pre Cleaned Yes	PLR SVP 06X
Operator MT		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Not Specified	Alternative ID 1

Town or Village:	Nottingham	Inspection Direction:	Upstream	Upstream Node:	SVP 06
Road:	Plot 8	Inspected Length:	7.57 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	7.57 m	Downstream Node:	FMH 03
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Post completion condition survey	Lining Material:	No Lining		

Comments:
Recommendations:




Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	0.0	0	0.0	0.0	0.0	0.0

Section Inspection - 26/05/2022 - FMH 03X

Item No. 14	Insp. No. 11	Date 26/05/22	Time 12:45	Client's Job Ref CASTLEWOOD	Weather No Rain Or Snow	Pre Cleaned Yes	PLR FMH 03X
Operator JC		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Not Specified	Alternative ID 1

Town or Village:	Nottingham	Inspection Direction:	Upstream	Upstream Node:	FMH 03
Road:	Plot 8	Inspected Length:	12.95 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	12.95 m	Downstream Node:	FMH 04
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Post completion condition survey	Lining Material:	No Lining		

Comments:
Recommendations:


Scale:	1:112	Position [m]	Code	Observation	MPEG	Photo	Grade																								
<div style="display: flex; align-items: center;"> <div style="margin-right: 20px;"> <p>Depth: m</p> <p>FMH 04</p>  </div> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 10%;"></td> <td style="width: 10%;"></td> <td style="width: 10%;">0.00</td> <td style="width: 10%;">MH</td> <td style="width: 40%;">Start node, manhole, reference: FMH 04</td> <td style="width: 10%;">00:00:00</td> <td style="width: 10%;"></td> <td style="width: 10%;"></td> </tr> <tr> <td></td> <td></td> <td>0.00</td> <td>WL</td> <td>Water level, 0% of the vertical dimension</td> <td>00:00:01</td> <td></td> <td></td> </tr> <tr> <td></td> <td></td> <td>12.95</td> <td>MHF</td> <td>Finish node, manhole, reference: FMH 03</td> <td>00:00:42</td> <td></td> <td></td> </tr> </table> </div>										0.00	MH	Start node, manhole, reference: FMH 04	00:00:00					0.00	WL	Water level, 0% of the vertical dimension	00:00:01					12.95	MHF	Finish node, manhole, reference: FMH 03	00:00:42		
		0.00	MH	Start node, manhole, reference: FMH 04	00:00:00																										
		0.00	WL	Water level, 0% of the vertical dimension	00:00:01																										
		12.95	MHF	Finish node, manhole, reference: FMH 03	00:00:42																										
Construction Features				Miscellaneous Features																											
Structural Defects				Service & Operational Observations																											
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade																						
0	0.0	0.0	0.0	0.0	0	0.0	0.0	0.0	0.0																						

Section Inspection - 26/05/2022 - SVP 07X

Item No. 15	Insp. No. 15	Date 26/05/22	Time 14:31	Client's Job Ref CASTLEWOOD	Weather No Rain Or Snow	Pre Cleaned Yes	PLR SVP 07X
Operator JC		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Not Specified	Alternative ID 1

Town or Village:	Nottingham	Inspection Direction:	Upstream	Upstream Node:	SVP 07
Road:	Plot 8	Inspected Length:	1.45 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	1.45 m	Downstream Node:	FMH 04
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Post completion condition survey	Lining Material:	No Lining		

Comments:
Recommendations:

Scale:	1:50	Position [m]	Code	Observation	MPEG	Photo	Grade
		Depth: m					
		FMH 04					
			MH	Start node, manhole, reference: FMH 04	00:00:00		
		0.31	WL	Water level, 0% of the vertical dimension	00:00:00		
		0.31	JN	Junction at 10 o'clock, 100mm dia	00:00:01		
		1.45	BRF	Finish node, major connection without manhole, reference: SVP 07	00:00:14		
		SVP 07					
		Depth: m					


Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	0.0	0	0.0	0.0	0.0	0.0

Section Inspection - 26/05/2022 - FMH 04X

Item No. 16	Insp. No. 10	Date 26/05/22	Time 12:43	Client's Job Ref CASTLEWOOD	Weather No Rain Or Snow	Pre Cleaned Yes	PLR FMH 04X
Operator JC		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Not Specified	Alternative ID 1

Town or Village:	Nottingham	Inspection Direction:	Upstream	Upstream Node:	FMH 04
Road:	Plot 8	Inspected Length:	6.40 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	6.40 m	Downstream Node:	FMH 04A
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Post completion condition survey	Lining Material:	No Lining		

Comments:
Recommendations:




Section Inspection - 26/05/2022 - SVP 8X

Item No. 17	Insp. No. 16	Date 26/05/22	Time 14:35	Client's Job Ref CASTLEWOOD	Weather No Rain Or Snow	Pre Cleaned Yes	PLR SVP 8X
Operator JC		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Not Specified	Alternative ID 1

Town or Village:	Nottingham	Inspection Direction:	Upstream	Upstream Node:	SVP 8
Road:	Plot 8	Inspected Length:	9.59 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	9.59 m	Downstream Node:	FMH 04A
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Post completion condition survey	Lining Material:	No Lining		

Comments:
Recommendations:




Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	0.0	0	0.0	0.0	0.0	0.0

Section Inspection - 26/05/2022 - FMH 04AX

Item No. 18	Insp. No. 9	Date 26/05/22	Time 12:40	Client's Job Ref CASTLEWOOD	Weather No Rain Or Snow	Pre Cleaned Yes	PLR FMH 04AX
Operator JC		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Not Specified	Alternative ID 1

Town or Village:	Nottingham	Inspection Direction:	Upstream	Upstream Node:	FMH 04A
Road:	Plot 8	Inspected Length:	6.54 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	6.54 m	Downstream Node:	FMH 05
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Post completion condition survey	Lining Material:	No Lining		

Comments:
Recommendations:


Scale:	1:57	Position [m]	Code	Observation	MPEG	Photo	Grade												
<div style="display: flex; align-items: center;"> <div style="margin-right: 20px;"> <p>Depth: m FMH 05</p>  </div> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 15%; text-align: center;">0.00</td> <td style="width: 10%;">MH</td> <td style="width: 45%;">Start node, manhole, reference: FMH 04A</td> <td style="width: 10%; text-align: center;">00:00:00</td> </tr> <tr> <td style="text-align: center;">0.00</td> <td>WL</td> <td>Water level, 0% of the vertical dimension</td> <td style="text-align: center;">00:00:00</td> </tr> <tr> <td style="text-align: center;">6.54</td> <td>MHF</td> <td>Finish node, manhole, reference: FMH 05</td> <td style="text-align: center;">00:00:13</td> </tr> </table> </div>								0.00	MH	Start node, manhole, reference: FMH 04A	00:00:00	0.00	WL	Water level, 0% of the vertical dimension	00:00:00	6.54	MHF	Finish node, manhole, reference: FMH 05	00:00:13
0.00	MH	Start node, manhole, reference: FMH 04A	00:00:00																
0.00	WL	Water level, 0% of the vertical dimension	00:00:00																
6.54	MHF	Finish node, manhole, reference: FMH 05	00:00:13																
Construction Features				Miscellaneous Features															
Structural Defects				Service & Operational Observations															
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade										
0	0.0	0.0	0.0	0.0	0	0.0	0.0	0.0	0.0										

Section Inspection - 26/05/2022 - FMH 05X

Item No. 19	Insp. No. 13	Date 26/05/22	Time 12:50	Client's Job Ref CASTLEWOOD	Weather No Rain Or Snow	Pre Cleaned Yes	PLR FMH 05X
Operator JC		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Not Specified	Alternative ID 1

Town or Village:	Nottingham	Inspection Direction:	Downstream	Upstream Node:	FMH 05
Road:	Plot 8	Inspected Length:	10.93 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	10.93 m	Downstream Node:	FMH 06
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	150 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Post completion condition survey	Lining Material:	No Lining		

Comments:
Recommendations:




Section Inspection - 26/05/2022 - SIC 01X

Item No. 20	Insp. No. 2	Date 26/05/22	Time 8:48	Client's Job Ref CASTLEWOOD	Weather No Rain Or Snow	Pre Cleaned Yes	PLR SIC 01X
Operator JC		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Not Specified	Alternative ID 1

Town or Village:	Nottingham	Inspection Direction:	Upstream	Upstream Node:	SIC 01
Road:	Plot 8	Inspected Length:	67.49 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	67.49 m	Downstream Node:	SMH 01
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	225 mm		
Flow Control:	No flow control	Material:	Polypropylene		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Post completion condition survey	Lining Material:	No Lining		

Comments:
Recommendations:




Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	0.0	0	0.0	0.0	0.0	0.0

Section Inspection - 26/05/2022 - ACO 1X

Item No. 21	Insp. No. 1	Date 26/05/22	Time 8:59	Client's Job Ref CASTLEWOOD	Weather No Rain Or Snow	Pre Cleaned Yes	PLR ACO 1X
Operator JC		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Not Specified	Alternative ID 1

Town or Village:	Nottingham	Inspection Direction:	Upstream	Upstream Node:	ACO 1
Road:	Plot 8	Inspected Length:	19.51 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	19.51 m	Downstream Node:	SMH 01
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	150 mm		
Flow Control:	No flow control	Material:	Polyethylene		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Post completion condition survey	Lining Material:	No Lining		

Comments:
Recommendations:


Scale:	1:169	Position [m]	Code	Observation	MPEG	Photo	Grade																					
<div style="display: flex; align-items: center;"> <div style="margin-right: 20px;"> <p>Depth: m</p> <p>SMH 01</p>  </div> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 10%; text-align: center;">0.00</td> <td style="width: 10%;"></td> <td style="width: 10%; text-align: center;">MH</td> <td style="width: 40%;">Start node, manhole, reference: SMH 01</td> <td style="width: 10%; text-align: center;">00:00:00</td> <td></td> <td></td> </tr> <tr> <td style="text-align: center;">0.00</td> <td></td> <td style="text-align: center;">WL</td> <td style="color: blue;">Water level, 0% of the vertical dimension</td> <td style="text-align: center;">00:00:01</td> <td></td> <td></td> </tr> <tr> <td style="text-align: center;">19.51</td> <td></td> <td style="text-align: center;">GYF</td> <td>Finish node, gully, reference: ACO 1</td> <td style="text-align: center;">00:01:46</td> <td></td> <td></td> </tr> </table> </div>								0.00		MH	Start node, manhole, reference: SMH 01	00:00:00			0.00		WL	Water level, 0% of the vertical dimension	00:00:01			19.51		GYF	Finish node, gully, reference: ACO 1	00:01:46		
0.00		MH	Start node, manhole, reference: SMH 01	00:00:00																								
0.00		WL	Water level, 0% of the vertical dimension	00:00:01																								
19.51		GYF	Finish node, gully, reference: ACO 1	00:01:46																								
Construction Features				Miscellaneous Features																								
Structural Defects				Service & Operational Observations																								
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade																			
0	0.0	0.0	0.0	0.0	0	0.0	0.0	0.0	0.0																			

Section Inspection - 26/05/2022 - SMH 01X

Item No. 22	Insp. No. 5	Date 26/05/22	Time 9:45	Client's Job Ref CASTLEWOOD	Weather No Rain Or Snow	Pre Cleaned Yes	PLR SMH 01X
Operator JC		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Not Specified	Alternative ID 1

Town or Village:	Nottingham	Inspection Direction:	Upstream	Upstream Node:	SMH 01
Road:	Plot 8	Inspected Length:	58.11 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	58.11 m	Downstream Node:	SMH 04
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	300 mm		
Flow Control:	No flow control	Material:	Polypropylene		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Post completion condition survey	Lining Material:	No Lining		

Comments:
Recommendations:



Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	0.0	0	0.0	0.0	0.0	0.0

Section Inspection - 26/05/2022 - ACO 2X

Item No. 23	Insp. No. 3	Date 26/05/22	Time 9:02	Client's Job Ref CASTLEWOOD	Weather No Rain Or Snow	Pre Cleaned Yes	PLR ACO 2X
Operator JC		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Not Specified	Alternative ID 1

Town or Village:	Nottingham	Inspection Direction:	Upstream	Upstream Node:	ACO 2
Road:	Plot 8	Inspected Length:	4.13 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	4.13 m	Downstream Node:	SMH 03
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	150 mm		
Flow Control:	No flow control	Material:	Polypropylene		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Post completion condition survey	Lining Material:	No Lining		

Comments:
Recommendations:




STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	0.0	0	0.0	0.0	0.0	0.0

Section Inspection - 26/05/2022 - SMH 03X

Item No. 24	Insp. No. 6	Date 26/05/22	Time 9:56	Client's Job Ref CASTLEWOOD	Weather No Rain Or Snow	Pre Cleaned Yes	PLR SMH 03X
Operator JC		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Not Specified	Alternative ID 1

Town or Village:	Nottingham	Inspection Direction:	Downstream	Upstream Node:	SMH 03
Road:	Plot 8	Inspected Length:	41.93 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	41.93 m	Downstream Node:	SMH 04
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	150 mm		
Flow Control:	No flow control	Material:	Polypropylene		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Post completion condition survey	Lining Material:	No Lining		

Comments:
Recommendations:


Scale:	1:362	Position [m]	Code	Observation	MPEG	Photo	Grade																								
<div style="display: flex; align-items: center;"> <div style="margin-right: 20px;"> <p>Depth: m</p> <p>SMH 03</p>  </div> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 10%; text-align: center;">0.00</td> <td style="width: 10%;"></td> <td style="width: 10%; text-align: center;">MH</td> <td style="width: 40%;">Start node, manhole, reference: SMH 03</td> <td style="width: 10%; text-align: center;">00:00:00</td> <td></td> <td></td> <td></td> </tr> <tr> <td style="text-align: center;">0.00</td> <td></td> <td style="text-align: center;">WL</td> <td style="color: blue;">Water level, 0% of the vertical dimension</td> <td style="text-align: center;">00:00:00</td> <td></td> <td></td> <td></td> </tr> <tr> <td style="text-align: center;">41.93</td> <td></td> <td style="text-align: center;">MHF</td> <td>Finish node, manhole, reference: SMH 04</td> <td style="text-align: center;">00:04:41</td> <td></td> <td></td> <td></td> </tr> </table> </div>								0.00		MH	Start node, manhole, reference: SMH 03	00:00:00				0.00		WL	Water level, 0% of the vertical dimension	00:00:00				41.93		MHF	Finish node, manhole, reference: SMH 04	00:04:41			
0.00		MH	Start node, manhole, reference: SMH 03	00:00:00																											
0.00		WL	Water level, 0% of the vertical dimension	00:00:00																											
41.93		MHF	Finish node, manhole, reference: SMH 04	00:04:41																											
Construction Features				Miscellaneous Features																											
Structural Defects				Service & Operational Observations																											
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade																						
0	0.0	0.0	0.0	0.0	0	0.0	0.0	0.0	0.0																						

Section Inspection - 26/05/2022 - SMH 04X

Item No. 25	Insp. No. 8	Date 26/05/22	Time 10:22	Client's Job Ref CASTLEWOOD	Weather No Rain Or Snow	Pre Cleaned Yes	PLR SMH 04X
Operator JC		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Not Specified	Alternative ID 1

Town or Village:	Nottingham	Inspection Direction:	Upstream	Upstream Node:	SMH 04
Road:	Plot 8	Inspected Length:	14.01 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	14.01 m	Downstream Node:	SMH 05
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	450 mm		
Flow Control:	No flow control	Material:	Polypropylene		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Post completion condition survey	Lining Material:	No Lining		

Comments:
Recommendations:


Scale:	1:121	Position [m]	Code	Observation	MPEG	Photo	Grade																								
<div style="display: flex; align-items: center;"> <div style="margin-right: 20px;"> <p>Depth: m</p> <p>SMH 05</p>  </div> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 10%;"></td> <td style="width: 10%;"></td> <td style="width: 10%;">0.00</td> <td style="width: 10%;">MH</td> <td style="width: 40%;">Start node, manhole, reference: SMH 05</td> <td style="width: 10%;">00:00:01</td> <td></td> <td></td> </tr> <tr> <td></td> <td></td> <td style="color: blue;">0.00</td> <td style="color: blue;">WL</td> <td style="color: blue;">Water level, 0% of the vertical dimension</td> <td style="color: blue;">00:00:01</td> <td></td> <td></td> </tr> <tr> <td></td> <td></td> <td style="border-top: 1px solid black;">14.01</td> <td style="border-top: 1px solid black;">MHF</td> <td style="border-top: 1px solid black;">Finish node, manhole, reference: SMH 04</td> <td style="border-top: 1px solid black;">00:00:59</td> <td></td> <td></td> </tr> </table> </div>										0.00	MH	Start node, manhole, reference: SMH 05	00:00:01					0.00	WL	Water level, 0% of the vertical dimension	00:00:01					14.01	MHF	Finish node, manhole, reference: SMH 04	00:00:59		
		0.00	MH	Start node, manhole, reference: SMH 05	00:00:01																										
		0.00	WL	Water level, 0% of the vertical dimension	00:00:01																										
		14.01	MHF	Finish node, manhole, reference: SMH 04	00:00:59																										
Construction Features				Miscellaneous Features																											
Structural Defects				Service & Operational Observations																											
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade																						
0	0.0	0.0	0.0	0.0	0	0.0	0.0	0.0	0.0																						

Section Inspection - 26/05/2022 - ACO 3X

Item No. 26	Insp. No. 7	Date 26/05/22	Time 10:12	Client's Job Ref CASTLEWOOD	Weather No Rain Or Snow	Pre Cleaned Yes	PLR ACO 3X
Operator JC		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Not Specified	Alternative ID 1

Town or Village:	Nottingham	Inspection Direction:	Upstream	Upstream Node:	ACO 3
Road:	Plot 8	Inspected Length:	1.50 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	1.50 m	Downstream Node:	SMH 05
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	150 mm		
Flow Control:	No flow control	Material:	Polypropylene		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Post completion condition survey	Lining Material:	No Lining		

Comments:
Recommendations:




Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	0.0	0	0.0	0.0	0.0	0.0

Section Inspection - 26/05/2022 - SMH 05X

Item No. 27	Insp. No. 9	Date 26/05/22	Time 13:12	Client's Job Ref CASTLEWOOD	Weather No Rain Or Snow	Pre Cleaned Yes	PLR SMH 05X
Operator JC		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Not Specified	Alternative ID 1

Town or Village:	Nottingham	Inspection Direction:	Upstream	Upstream Node:	SMH 05
Road:	Plot 8	Inspected Length:	39.25 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	39.25 m	Downstream Node:	SMH 06
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	450 mm		
Flow Control:	No flow control	Material:	Polypropylene		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Post completion condition survey	Lining Material:	No Lining		

Comments:
Recommendations:


Scale:	1:339	Position [m]	Code	Observation	MPEG	Photo	Grade																																										
<div style="display: flex; align-items: center;"> <div style="flex: 1;"> <p style="margin: 0;">Depth: m</p> <p style="margin: 0;">SMH 06</p>  </div> <table border="1" style="margin-left: 10px; border-collapse: collapse;"> <tr> <td style="width: 10%; text-align: right;">0.00</td> <td style="width: 10%;"></td> <td style="width: 10%;">MH</td> <td style="width: 40%;">Start node, manhole, reference: SMH 06</td> <td style="width: 10%;">00:00:00</td> <td></td> <td></td> </tr> <tr> <td style="text-align: right;">0.00</td> <td></td> <td>WL</td> <td>Water level, 0% of the vertical dimension</td> <td>00:00:00</td> <td></td> <td></td> </tr> <tr> <td style="text-align: right;">5.72</td> <td></td> <td>CN</td> <td>Connection other than junction at 11 o'clock, 150mm dia</td> <td>00:00:30</td> <td></td> <td></td> </tr> <tr> <td style="text-align: right;">6.71</td> <td></td> <td>CN</td> <td>Connection other than junction at 1 o'clock, 150mm dia</td> <td>00:00:39</td> <td></td> <td></td> </tr> <tr> <td style="text-align: right;">7.50</td> <td></td> <td>CN</td> <td>Connection other than junction at 11 o'clock, 150mm dia</td> <td>00:00:46</td> <td></td> <td></td> </tr> <tr> <td style="text-align: right;">39.25</td> <td></td> <td>MHF</td> <td>Finish node, manhole, reference: SMH 05</td> <td>00:02:58</td> <td></td> <td></td> </tr> </table> </div>								0.00		MH	Start node, manhole, reference: SMH 06	00:00:00			0.00		WL	Water level, 0% of the vertical dimension	00:00:00			5.72		CN	Connection other than junction at 11 o'clock, 150mm dia	00:00:30			6.71		CN	Connection other than junction at 1 o'clock, 150mm dia	00:00:39			7.50		CN	Connection other than junction at 11 o'clock, 150mm dia	00:00:46			39.25		MHF	Finish node, manhole, reference: SMH 05	00:02:58		
0.00		MH	Start node, manhole, reference: SMH 06	00:00:00																																													
0.00		WL	Water level, 0% of the vertical dimension	00:00:00																																													
5.72		CN	Connection other than junction at 11 o'clock, 150mm dia	00:00:30																																													
6.71		CN	Connection other than junction at 1 o'clock, 150mm dia	00:00:39																																													
7.50		CN	Connection other than junction at 11 o'clock, 150mm dia	00:00:46																																													
39.25		MHF	Finish node, manhole, reference: SMH 05	00:02:58																																													
Construction Features				Miscellaneous Features																																													
Structural Defects				Service & Operational Observations																																													
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade																																								
0	0.0	0.0	0.0	0.0	0	0.0	0.0	0.0	0.0																																								

Section Inspection - 26/05/2022 - G1X

Item No. 28	Insp. No. 10	Date 26/05/22	Time 13:22	Client's Job Ref CASTLEWOOD	Weather No Rain Or Snow	Pre Cleaned Yes	PLR G1X
Operator JC		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Not Specified	Alternative ID 1

Town or Village:	Nottingham	Inspection Direction:	Upstream	Upstream Node:	G1
Road:	Plot 8	Inspected Length:	11.65 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	11.65 m	Downstream Node:	SMH 06
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	150 mm		
Flow Control:	No flow control	Material:	Polypropylene		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Post completion condition survey	Lining Material:	No Lining		

Comments:
Recommendations:




Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	0.0	0	0.0	0.0	0.0	0.0

Section Inspection - 26/05/2022 - G2X

Item No. 29	Insp. No. 11	Date 26/05/22	Time 13:27	Client's Job Ref CASTLEWOOD	Weather No Rain Or Snow	Pre Cleaned Yes	PLR G2X
Operator JC		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Not Specified	Alternative ID 1

Town or Village:	Nottingham	Inspection Direction:	Upstream	Upstream Node:	G2
Road:	Plot 8	Inspected Length:	16.23 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	16.23 m	Downstream Node:	SMH 06
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	150 mm		
Flow Control:	No flow control	Material:	Polypropylene		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Post completion condition survey	Lining Material:	No Lining		

Comments:
Recommendations:




Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	0.0	0	0.0	0.0	0.0	0.0

Section Inspection - 26/05/2022 - ACO 4X

Item No. 30	Insp. No. 12	Date 26/05/22	Time 13:32	Client's Job Ref CASTLEWOOD	Weather No Rain Or Snow	Pre Cleaned Yes	PLR ACO 4X
Operator JC		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Not Specified	Alternative ID 1

Town or Village:	Nottingham	Inspection Direction:	Upstream	Upstream Node:	ACO 4
Road:	Plot 8	Inspected Length:	15.49 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	15.49 m	Downstream Node:	SMH 06
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	150 mm		
Flow Control:	No flow control	Material:	Polypropylene		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Post completion condition survey	Lining Material:	No Lining		

Comments:
Recommendations:




Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	0.0	0	0.0	0.0	0.0	0.0

Section Inspection - 26/05/2022 - SMH 06X

Item No. 31	Insp. No. 14	Date 26/05/22	Time 13:49	Client's Job Ref CASTLEWOOD	Weather No Rain Or Snow	Pre Cleaned Yes	PLR SMH 06X
Operator JC		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Not Specified	Alternative ID 1

Town or Village:	Nottingham	Inspection Direction:	Upstream	Upstream Node:	SMH 06
Road:	Plot 8	Inspected Length:	33.04 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	33.04 m	Downstream Node:	SMH 07
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	450 mm		
Flow Control:	No flow control	Material:	Polypropylene		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Post completion condition survey	Lining Material:	No Lining		

Comments:
Recommendations:




Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	0.0	0	0.0	0.0	0.0	0.0

Section Inspection - 26/05/2022 - ACO 5X

Item No. 32	Insp. No. 13	Date 26/05/22	Time 13:45	Client's Job Ref CASTLEWOOD	Weather No Rain Or Snow	Pre Cleaned Yes	PLR ACO 5X
Operator JC		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Not Specified	Alternative ID 1

Town or Village:	Nottingham	Inspection Direction:	Upstream	Upstream Node:	ACO 5
Road:	Plot 8	Inspected Length:	8.64 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	8.64 m	Downstream Node:	SMH 07
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	150 mm		
Flow Control:	No flow control	Material:	Polypropylene		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Post completion condition survey	Lining Material:	No Lining		

Comments:
Recommendations:




Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	0.0	0	0.0	0.0	0.0	0.0

Section Inspection - 26/05/2022 - SMH 07X

Item No. 33	Insp. No. 15	Date 26/05/22	Time 14:00	Client's Job Ref CASTLEWOOD	Weather No Rain Or Snow	Pre Cleaned Yes	PLR SMH 07X
Operator JC		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Not Specified	Alternative ID 1

Town or Village:	Nottingham	Inspection Direction:	Downstream	Upstream Node:	SMH 07
Road:	Plot 8	Inspected Length:	1.54 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	1.54 m	Downstream Node:	INT 2
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	450 mm		
Flow Control:	No flow control	Material:	Polypropylene		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Post completion condition survey	Lining Material:	No Lining		

Comments:
Recommendations:

Scale:	1:50	Position [m]	Code	Observation	MPEG	Photo	Grade																					
<div style="display: flex; align-items: center;"> <div style="margin-right: 20px;"> <p>Depth: m</p> <p>SMH 07</p>  <p>INT 2 Depth: m</p> </div> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 10%; text-align: center;">0.00</td> <td style="width: 10%; text-align: center;">MH</td> <td style="width: 40%;">Start node, manhole, reference: SMH 07</td> <td style="width: 10%; text-align: center;">00:00:00</td> <td></td> <td></td> <td></td> </tr> <tr> <td style="width: 10%; text-align: center;">0.00</td> <td style="width: 10%; text-align: center;">WL</td> <td style="width: 40%;">Water level, 0% of the vertical dimension</td> <td style="width: 10%; text-align: center;">00:00:00</td> <td></td> <td></td> <td></td> </tr> <tr> <td style="width: 10%; text-align: center;">1.54</td> <td style="width: 10%; text-align: center;">OSF</td> <td style="width: 40%;">Finish node, oil separator, reference: INT 2: TANK</td> <td style="width: 10%; text-align: center;">00:00:09</td> <td></td> <td></td> <td></td> </tr> </table> </div>								0.00	MH	Start node, manhole, reference: SMH 07	00:00:00				0.00	WL	Water level, 0% of the vertical dimension	00:00:00				1.54	OSF	Finish node, oil separator, reference: INT 2: TANK	00:00:09			
0.00	MH	Start node, manhole, reference: SMH 07	00:00:00																									
0.00	WL	Water level, 0% of the vertical dimension	00:00:00																									
1.54	OSF	Finish node, oil separator, reference: INT 2: TANK	00:00:09																									


Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	0.0	0	0.0	0.0	0.0	0.0

Section Inspection - 26/05/2022 - INT 2X

Item No. 34	Insp. No. 16	Date 26/05/22	Time 14:12	Client's Job Ref CASTLEWOOD	Weather No Rain Or Snow	Pre Cleaned Yes	PLR INT 2X
Operator JC		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Not Specified	Alternative ID 1

Town or Village:	Nottingham	Inspection Direction:	Upstream	Upstream Node:	INT 2
Road:	Plot 8	Inspected Length:	12.25 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	12.25 m	Downstream Node:	SMH 17
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	450 mm		
Flow Control:	No flow control	Material:	Polypropylene		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Post completion condition survey	Lining Material:	No Lining		

Comments:
Recommendations:

Scale:	1:106	Position [m]	Code	Observation	MPEG	Photo	Grade																								
<div style="display: flex; align-items: center;"> <div style="margin-right: 20px;"> <p>Depth: m</p> <p>SMH 17</p>  </div> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 10%;"></td> <td style="width: 10%; text-align: center;">0.00</td> <td style="width: 10%;"></td> <td style="width: 10%;">MH</td> <td style="width: 40%;">Start node, manhole, reference: SMH 17</td> <td style="width: 10%; text-align: center;">00:00:00</td> <td></td> <td></td> </tr> <tr> <td></td> <td style="text-align: center;">0.00</td> <td></td> <td>WL</td> <td>Water level, 0% of the vertical dimension</td> <td style="text-align: center;">00:00:00</td> <td></td> <td></td> </tr> <tr> <td></td> <td style="text-align: center;">12.25</td> <td></td> <td>OSF</td> <td>Finish node, oil separator, reference: INT 2: TANK</td> <td style="text-align: center;">00:01:12</td> <td></td> <td></td> </tr> </table> </div>									0.00		MH	Start node, manhole, reference: SMH 17	00:00:00				0.00		WL	Water level, 0% of the vertical dimension	00:00:00				12.25		OSF	Finish node, oil separator, reference: INT 2: TANK	00:01:12		
	0.00		MH	Start node, manhole, reference: SMH 17	00:00:00																										
	0.00		WL	Water level, 0% of the vertical dimension	00:00:00																										
	12.25		OSF	Finish node, oil separator, reference: INT 2: TANK	00:01:12																										


Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	0.0	0	0.0	0.0	0.0	0.0

Section Inspection - 27/05/2022 - ACO 7X

Item No. 35	Insp. No. 20	Date 27/05/22	Time 8:35	Client's Job Ref CASTLEWOOD	Weather No Rain Or Snow	Pre Cleaned Yes	PLR ACO 7X
Operator JC		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Not Specified	Alternative ID 1

Town or Village:	Nottingham	Inspection Direction:	Upstream	Upstream Node:	ACO 7
Road:	Plot 8	Inspected Length:	12.66 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	12.66 m	Downstream Node:	SMH 08
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	150 mm		
Flow Control:	No flow control	Material:	Polyethylene		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Post completion condition survey	Lining Material:	No Lining		

Comments:
Recommendations:



Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	0.0	0	0.0	0.0	0.0	0.0

Section Inspection - 27/05/2022 - ACO 8X

Item No. 36	Insp. No. 19	Date 27/05/22	Time 8:33	Client's Job Ref CASTLEWOOD	Weather No Rain Or Snow	Pre Cleaned Yes	PLR ACO 8X
Operator JC		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Not Specified	Alternative ID 1

Town or Village:	Nottingham	Inspection Direction:	Upstream	Upstream Node:	ACO 8
Road:	Plot 8	Inspected Length:	3.15 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	3.15 m	Downstream Node:	SMH 08
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	150 mm		
Flow Control:	No flow control	Material:	Polyethylene		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Post completion condition survey	Lining Material:	No Lining		

Comments:
Recommendations:




Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	0.0	0	0.0	0.0	0.0	0.0

Section Inspection - 27/05/2022 - PSO 3X

Item No. 37	Insp. No. 21	Date 27/05/22	Time 8:37	Client's Job Ref CASTLEWOOD	Weather No Rain Or Snow	Pre Cleaned Yes	PLR PSO 3X
Operator JC		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Not Specified	Alternative ID 1

Town or Village:	Nottingham	Inspection Direction:	Upstream	Upstream Node:	PSO 3
Road:	Plot 8	Inspected Length:	0.61 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	0.61 m	Downstream Node:	SMH 08
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	150 mm		
Flow Control:	No flow control	Material:	Polyethylene		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Post completion condition survey	Lining Material:	No Lining		

Comments:
Recommendations:

Scale:	1:50	Position [m]	Code	Observation	MPEG	Photo	Grade
		Depth: m SMH 08					
			MH	Start node, manhole, reference: SMH 08	00:00:00		
		0.04	WL	Water level, 0% of the vertical dimension	00:00:00		
		0.22	SC	Pipe size changes, new size(s), 100mm high	00:00:04		
		0.61	BRF	Finish node, major connection without manhole, reference: PSO 3	00:00:09		
		Depth: m					


Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	0.0	0	0.0	0.0	0.0	0.0

Section Inspection - 27/05/2022 - SMH 08X

Item No. 38	Insp. No. 4	Date 27/05/22	Time 8:37	Client's Job Ref CASTLEWOOD	Weather No Rain Or Snow	Pre Cleaned Yes	PLR SMH 08X
Operator MT		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Not Specified	Alternative ID 1

Town or Village:	Nottingham	Inspection Direction:	Upstream	Upstream Node:	SMH 08
Road:	Plot 8	Inspected Length:	14.82 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	14.82 m	Downstream Node:	SMH 09
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	375 mm		
Flow Control:	No flow control	Material:	Polyethylene		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Post completion condition survey	Lining Material:	No Lining		

Comments:
Recommendations:




Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	0.0	0	0.0	0.0	0.0	0.0

Section Inspection - 27/05/2022 - SMH 09X

Item No. 39	Insp. No. 18	Date 27/05/22	Time 8:12	Client's Job Ref CASTLEWOOD	Weather No Rain Or Snow	Pre Cleaned Yes	PLR SMH 09X
Operator JC		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Not Specified	Alternative ID 1

Town or Village:	Nottingham	Inspection Direction:	Upstream	Upstream Node:	SMH 09
Road:	Plot 8	Inspected Length:	71.20 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	71.20 m	Downstream Node:	SMH 11
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	375 mm		
Flow Control:	No flow control	Material:	Polypropylene		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Post completion condition survey	Lining Material:	No Lining		

Comments:
Recommendations:


Scale:	1:614	Position [m]	Code	Observation	MPEG	Photo	Grade																								
<div style="display: flex; align-items: center;"> <div style="margin-right: 20px;"> <p>Depth: m</p> <p>SMH 11</p>  </div> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 10%;"></td> <td style="width: 10%; text-align: center;">0.00</td> <td style="width: 10%;"></td> <td style="width: 10%;">MH</td> <td style="width: 40%;">Start node, manhole, reference: SMH 11</td> <td style="width: 10%; text-align: center;">00:00:01</td> <td></td> <td></td> </tr> <tr> <td></td> <td style="text-align: center;">0.00</td> <td></td> <td>WL</td> <td>Water level, 0% of the vertical dimension</td> <td style="text-align: center;">00:00:02</td> <td></td> <td></td> </tr> <tr> <td></td> <td style="text-align: center;">71.20</td> <td></td> <td>MHF</td> <td>Finish node, manhole, reference: SMH 09</td> <td style="text-align: center;">00:06:10</td> <td></td> <td></td> </tr> </table> </div>									0.00		MH	Start node, manhole, reference: SMH 11	00:00:01				0.00		WL	Water level, 0% of the vertical dimension	00:00:02				71.20		MHF	Finish node, manhole, reference: SMH 09	00:06:10		
	0.00		MH	Start node, manhole, reference: SMH 11	00:00:01																										
	0.00		WL	Water level, 0% of the vertical dimension	00:00:02																										
	71.20		MHF	Finish node, manhole, reference: SMH 09	00:06:10																										
Construction Features				Miscellaneous Features																											
Structural Defects				Service & Operational Observations																											
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade																						
0	0.0	0.0	0.0	0.0	0	0.0	0.0	0.0	0.0																						

Section Inspection - 27/05/2022 - PSO 1X

Item No. 40	Insp. No. 17	Date 27/05/22	Time 8:09	Client's Job Ref CASTLEWOOD	Weather No Rain Or Snow	Pre Cleaned Yes	PLR PSO 1X
Operator JC		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Not Specified	Alternative ID 1

Town or Village:	Nottingham	Inspection Direction:	Upstream	Upstream Node:	PSO 1
Road:	Plot 8	Inspected Length:	4.57 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	4.57 m	Downstream Node:	SMH 10
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	150 mm		
Flow Control:	No flow control	Material:	Polyethylene		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Post completion condition survey	Lining Material:	No Lining		

Comments:
Recommendations:




STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	0.0	0	0.0	0.0	0.0	0.0

Section Inspection - 27/05/2022 - PSO 2X

Item No. 41	Insp. No. 18	Date 27/05/22	Time 8:11	Client's Job Ref CASTLEWOOD	Weather No Rain Or Snow	Pre Cleaned Yes	PLR PSO 2X
Operator JC		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Not Specified	Alternative ID 1

Town or Village:	Nottingham	Inspection Direction:	Upstream	Upstream Node:	PSO 2
Road:	Plot 8	Inspected Length:	4.38 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	4.38 m	Downstream Node:	SMH 10
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	150 mm		
Flow Control:	No flow control	Material:	Polyethylene		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Post completion condition survey	Lining Material:	No Lining		

Comments:
Recommendations:




STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	0.0	0	0.0	0.0	0.0	0.0

Section Inspection - 27/05/2022 - SMH 10X

Item No. 42	Insp. No. 17	Date 27/05/22	Time 7:28	Client's Job Ref CASTLEWOOD	Weather No Rain Or Snow	Pre Cleaned Yes	PLR SMH 10X
Operator JC		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Not Specified	Alternative ID 1

Town or Village:	Nottingham	Inspection Direction:	Upstream	Upstream Node:	SMH 10
Road:	Plot 8	Inspected Length:	13.43 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	13.43 m	Downstream Node:	SMH 11
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	450 mm		
Flow Control:	No flow control	Material:	Polypropylene		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Post completion condition survey	Lining Material:	No Lining		

Comments:
Recommendations:


Scale:	1:116	Position [m]	Code	Observation	MPEG	Photo	Grade																								
<div style="display: flex; align-items: center;"> <div style="margin-right: 20px;"> <p>Depth: m</p> <p>SMH 11</p>  </div> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 10%;"></td> <td style="width: 10%; text-align: center;">0.00</td> <td style="width: 10%;"></td> <td style="width: 10%;">MH</td> <td style="width: 40%;">Start node, manhole, reference: SMH 11</td> <td style="width: 10%; text-align: center;">00:00:00</td> <td style="width: 10%;"></td> <td style="width: 10%;"></td> </tr> <tr> <td></td> <td style="text-align: center;">0.00</td> <td></td> <td>WL</td> <td>Water level, 0% of the vertical dimension</td> <td style="text-align: center;">00:00:00</td> <td></td> <td></td> </tr> <tr> <td></td> <td style="text-align: center;">13.43</td> <td></td> <td>MHF</td> <td>Finish node, manhole, reference: SMH 10</td> <td style="text-align: center;">00:00:58</td> <td></td> <td></td> </tr> </table> </div>									0.00		MH	Start node, manhole, reference: SMH 11	00:00:00				0.00		WL	Water level, 0% of the vertical dimension	00:00:00				13.43		MHF	Finish node, manhole, reference: SMH 10	00:00:58		
	0.00		MH	Start node, manhole, reference: SMH 11	00:00:00																										
	0.00		WL	Water level, 0% of the vertical dimension	00:00:00																										
	13.43		MHF	Finish node, manhole, reference: SMH 10	00:00:58																										
Construction Features				Miscellaneous Features																											
Structural Defects				Service & Operational Observations																											
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade																						
0	0.0	0.0	0.0	0.0	0	0.0	0.0	0.0	0.0																						

Section Inspection - 27/05/2022 - SMH 11X

Item No. 43	Insp. No. 3	Date 27/05/22	Time 8:09	Client's Job Ref CASTLEWOOD	Weather No Rain Or Snow	Pre Cleaned Yes	PLR SMH 11X
Operator MT		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Not Specified	Alternative ID 1

Town or Village:	Nottingham	Inspection Direction:	Upstream	Upstream Node:	SMH 11
Road:	Plot 8	Inspected Length:	8.70 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	8.70 m	Downstream Node:	SMH 16
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	375 mm		
Flow Control:	No flow control	Material:	Polyethylene		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Post completion condition survey	Lining Material:	No Lining		

Comments:
Recommendations:


Scale:	1:75	Position [m]	Code	Observation	MPEG	Photo	Grade																								
<div style="display: flex; align-items: center;"> <div style="margin-right: 20px;"> <p>Depth: m</p> <p>SMH 16</p>  </div> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 10%; text-align: center;">0.00</td> <td style="width: 10%;"></td> <td style="width: 10%; text-align: center;">MH</td> <td style="width: 40%;">Start node, manhole, reference: SMH 16</td> <td style="width: 10%; text-align: center;">00:00:00</td> <td></td> <td></td> <td></td> </tr> <tr> <td style="width: 10%; text-align: center;">0.00</td> <td style="width: 10%;"></td> <td style="width: 10%; text-align: center;">WL</td> <td style="width: 40%;">Water level, 0% of the vertical dimension</td> <td style="width: 10%; text-align: center;">00:00:00</td> <td></td> <td></td> <td></td> </tr> <tr> <td style="width: 10%; text-align: center;">8.70</td> <td style="width: 10%;"></td> <td style="width: 10%; text-align: center;">MHF</td> <td style="width: 40%;">Finish node, manhole, reference: SMH 11</td> <td style="width: 10%; text-align: center;">00:00:38</td> <td></td> <td></td> <td></td> </tr> </table> </div>								0.00		MH	Start node, manhole, reference: SMH 16	00:00:00				0.00		WL	Water level, 0% of the vertical dimension	00:00:00				8.70		MHF	Finish node, manhole, reference: SMH 11	00:00:38			
0.00		MH	Start node, manhole, reference: SMH 16	00:00:00																											
0.00		WL	Water level, 0% of the vertical dimension	00:00:00																											
8.70		MHF	Finish node, manhole, reference: SMH 11	00:00:38																											
Construction Features				Miscellaneous Features																											
Structural Defects				Service & Operational Observations																											
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade																						
0	0.0	0.0	0.0	0.0	0	0.0	0.0	0.0	0.0																						

Section Inspection - 27/05/2022 - ACO 10X

Item No. 44	Insp. No. 20	Date 27/05/22	Time 11:10	Client's Job Ref CASTLEWOOD	Weather No Rain Or Snow	Pre Cleaned Yes	PLR ACO 10X
Operator JC		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Not Specified	Alternative ID 1

Town or Village:	Nottingham	Inspection Direction:	Upstream	Upstream Node:	ACO 10
Road:	Plot 8	Inspected Length:	2.75 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	2.75 m	Downstream Node:	SMH 13
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	225 mm		
Flow Control:	No flow control	Material:	Polypropylene		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Post completion condition survey	Lining Material:	No Lining		

Comments:
Recommendations:




STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	0.0	0	0.0	0.0	0.0	0.0

Section Inspection - 27/05/2022 - SMH 13X

Item No. 45	Insp. No. 21	Date 27/05/22	Time 11:13	Client's Job Ref CASTLEWOOD	Weather No Rain Or Snow	Pre Cleaned Yes	PLR SMH 13X
Operator JC		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Not Specified	Alternative ID 1

Town or Village:	Nottingham	Inspection Direction:	Downstream	Upstream Node:	SMH 13
Road:	Plot 8	Inspected Length:	1.91 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	1.91 m	Downstream Node:	INT 1
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	225 mm		
Flow Control:	No flow control	Material:	Polypropylene		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Post completion condition survey	Lining Material:	No Lining		

Comments:
Recommendations:

Scale:	1:50	Position [m]	Code	Observation	MPEG	Photo	Grade																								
<div style="display: flex; align-items: center;"> <div style="margin-right: 20px;"> <p>Depth: m SMH 13</p>  </div> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 10%;"></td> <td style="width: 10%;">0.00</td> <td style="width: 10%;">MH</td> <td style="width: 40%;">Start node, manhole, reference: SMH 13</td> <td style="width: 10%;">00:00:00</td> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td>0.00</td> <td>WL</td> <td>Water level, 0% of the vertical dimension</td> <td>00:00:01</td> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td>1.91</td> <td>OSF</td> <td>Finish node, oil separator, reference: INT 1: TANK</td> <td>00:00:22</td> <td></td> <td></td> <td></td> </tr> </table> </div>									0.00	MH	Start node, manhole, reference: SMH 13	00:00:00					0.00	WL	Water level, 0% of the vertical dimension	00:00:01					1.91	OSF	Finish node, oil separator, reference: INT 1: TANK	00:00:22			
	0.00	MH	Start node, manhole, reference: SMH 13	00:00:00																											
	0.00	WL	Water level, 0% of the vertical dimension	00:00:01																											
	1.91	OSF	Finish node, oil separator, reference: INT 1: TANK	00:00:22																											


Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	0.0	0	0.0	0.0	0.0	0.0

Section Inspection - 22/06/2022 - INT 1X

Item No. 46	Insp. No. 6	Date 22/06/22	Time 12:13	Client's Job Ref CASTLEWOOD	Weather No Rain Or Snow	Pre Cleaned Yes	PLR INT 1X
Operator JN		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Not Specified	Alternative ID 1

Town or Village:	Nottingham	Inspection Direction:	Upstream	Upstream Node:	INT 1
Road:	Plot 8	Inspected Length:	12.27 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	12.27 m	Downstream Node:	SWMH16
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	225 mm		
Flow Control:	No flow control	Material:	Polyethylene		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Post completion condition survey	Lining Material:	No Lining		

Comments:
Recommendations:




Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	0.0	0	0.0	0.0	0.0	0.0

Section Inspection - 22/06/2022 - G6X

Item No. 47	Insp. No. 10	Date 22/06/22	Time 14:05	Client's Job Ref CASTLEWOOD	Weather No Rain Or Snow	Pre Cleaned Yes	PLR G6X
Operator JN		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Not Specified	Alternative ID 1

Town or Village:	Nottingham	Inspection Direction:	Upstream	Upstream Node:	G6
Road:	Plot 8	Inspected Length:	5.13 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	5.13 m	Downstream Node:	SWMH 15
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	150 mm		
Flow Control:	No flow control	Material:	Polyethylene		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Post completion condition survey	Lining Material:	No Lining		

Comments:
Recommendations:




Section Inspection - 22/06/2022 - G8X

Item No. 48	Insp. No. 7	Date 22/06/22	Time 13:53	Client's Job Ref CASTLEWOOD	Weather No Rain Or Snow	Pre Cleaned Yes	PLR G8X
Operator MT		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Not Specified	Alternative ID 1

Town or Village:	Nottingham	Inspection Direction:	Upstream	Upstream Node:	G8
Road:	Plot 8	Inspected Length:	7.33 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	7.33 m	Downstream Node:	SWMH 15
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	150 mm		
Flow Control:	No flow control	Material:	Polyethylene		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Post completion condition survey	Lining Material:	No Lining		

Comments:
Recommendations:




Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	0.0	0	0.0	0.0	0.0	0.0

Section Inspection - 22/06/2022 - G9X

Item No. 49	Insp. No. 8	Date 22/06/22	Time 13:55	Client's Job Ref CASTLEWOOD	Weather No Rain Or Snow	Pre Cleaned Yes	PLR G9X
Operator MT		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Not Specified	Alternative ID 1

Town or Village:	Nottingham	Inspection Direction:	Upstream	Upstream Node:	G9
Road:	Plot 8	Inspected Length:	16.88 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	16.88 m	Downstream Node:	SWMH 15
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	150 mm		
Flow Control:	No flow control	Material:	Polyethylene		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Post completion condition survey	Lining Material:	No Lining		

Comments:
Recommendations:




Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	0.0	0	0.0	0.0	0.0	0.0

Section Inspection - 22/06/2022 - G10X

Item No. 50	Insp. No. 9	Date 22/06/22	Time 14:00	Client's Job Ref CASTLEWOOD	Weather No Rain Or Snow	Pre Cleaned Yes	PLR G10X
Operator JN		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Not Specified	Alternative ID 1

Town or Village:	Nottingham	Inspection Direction:	Upstream	Upstream Node:	G10
Road:	Plot 8	Inspected Length:	15.89 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	15.89 m	Downstream Node:	SWMH 15
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	150 mm		
Flow Control:	No flow control	Material:	Polyethylene		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Post completion condition survey	Lining Material:	No Lining		

Comments:
Recommendations:




Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	0.0	0	0.0	0.0	0.0	0.0

Section Inspection - 22/07/2022 - SMH15X

Item No. 51	Insp. No. 1	Date 22/07/22	Time 11:10	Client's Job Ref CASTLEWOOD	Weather Rain	Pre Cleaned Yes	PLR SMH15X
Operator SC		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Not Specified	Alternative ID 1

Town or Village:	Nottingham	Inspection Direction:	Downstream	Upstream Node:	SMH15
Road:	Plot 8	Inspected Length:	6.44 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	6.44 m	Downstream Node:	SMH16
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	225 mm		
Flow Control:	No flow control	Material:	Polyethylene		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Post completion condition survey	Lining Material:	No Lining		

Comments:
Recommendations:




Section Inspection - 27/05/2022 - SMH 16X

Item No. 52	Insp. No. 1	Date 27/05/22	Time 7:21	Client's Job Ref CASTLEWOOD	Weather No Rain Or Snow	Pre Cleaned Yes	PLR SMH 16X
Operator MT		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Not Specified	Alternative ID 1

Town or Village:	Nottingham	Inspection Direction:	Upstream	Upstream Node:	SMH 16
Road:	Plot 8	Inspected Length:	23.36 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	23.36 m	Downstream Node:	SMH 17
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	375 mm		
Flow Control:	No flow control	Material:	Polyethylene		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Post completion condition survey	Lining Material:	No Lining		

Comments:
Recommendations:




Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	0.0	0	0.0	0.0	0.0	0.0

Section Inspection - 27/05/2022 - SMH 17X

Item No. 53	Insp. No. 2	Date 27/05/22	Time 7:31	Client's Job Ref CASTLEWOOD	Weather No Rain Or Snow	Pre Cleaned Yes	PLR SMH 17X
Operator MT		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Not Specified	Alternative ID 1

Town or Village:	Nottingham	Inspection Direction:	Downstream	Upstream Node:	SMH 17
Road:	Plot 8	Inspected Length:	15.92 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	15.92 m	Downstream Node:	SMH 18
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	450 mm		
Flow Control:	No flow control	Material:	Polyethylene		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Post completion condition survey	Lining Material:	No Lining		

Comments:
Recommendations:



Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	0.0	0	0.0	0.0	0.0	0.0